

RADIATION SAFETY DUTIES  
UPDATED: JULY 2007

CPT CODE: N/A

---

To comply with radiation safety requirements of the University of Wisconsin Radiation Safety Department and the Nuclear Regulatory Commission:

1. Wipe test must be completed on a weekly basis of the Nuclear Medicine Department.
2. GM monitoring must be completed on a daily basis of the Nuclear Medicine Department.
3. Bioassay must be done in accordance with Nuclear Medicine Bioassay protocol.
4. Personal radiation contamination monitoring must be completed at end of work shift or as needed on a daily basis.

---

Reviewed By: S. Perlman, D. Fuerbringer

---

Scott B. Perlman, MD, MS  
Chief, Nuclear Medicine

---

Derek Fuerbringer, CNMT  
Manager, Nuclear Medicine